

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

509

167/60/3/1

| FOR OFFICE USE ONLY | |
|---|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR. SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR. | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

IDENTIFICATION

| | |
|---|---------------------|
| 1. BUILDING NAME (Common) (Historic) | |
| NORTH GROSVENORDALE MILL HOUSING - TYPE F | |
| 2. TOWN CITY | VILLAGE |
| THOMPSON | NORTH GROSVENORDALE |
| 3. STREET AND NUMBER (and/or location) | |
| 1006 ROUTE 12 (983 RIVERSIDE DR.) | |
| 4. OWNER(S) | |
| MARTEL, RACHEL, N. GROSVENORDALE, CT 06255 | |
| 5. USE (Present) (Historic) | |
| Residence | |
| 6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES EXPLAIN | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |

DESCRIPTION

| | | |
|--|--|--|
| 7. STYLE OF BUILDING | | DATE OF CONSTRUCTION |
| Mill Housing | | c. 1885 |
| 8. MATERIALS (Indicate use or location when appropriate) | | |
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Walls Brick Chimney <input type="checkbox"/> Other (Specify) |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input checked="" type="checkbox"/> Fieldstone Foundation |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: | <input type="checkbox"/> Cut stone Type: |
| 9. STRUCTURAL SYSTEM | | |
| <input type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input type="checkbox"/> balloon |
| <input checked="" type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) | | |
| 10. ROOF (Type) | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile |
| <input type="checkbox"/> Slate | <input type="checkbox"/> Gable end to the street | |
| <input type="checkbox"/> Monitor | <input checked="" type="checkbox"/> Ridge parallel to the street | |
| <input type="checkbox"/> sawtooth | <input type="checkbox"/> Other (Specify) | |
| <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) | |
| 11. NUMBER OF STORIES | | APPROXIMATE DIMENSIONS |
| 1 1/2 | | 40' x 30' |
| 12. CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13. INTEGRITY (Location) | | WHEN? (Alterations) IF YES, EXPLAIN |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No See #17 |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input type="checkbox"/> Other landscape features or buildings (Specify) | | |
| <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15. SURROUNDING ENVIRONMENT | | |
| <input type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site | | |
| <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input checked="" type="checkbox"/> High building density | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| In a cluster of very similar mill housing just north of the North Grosvenordale mill. | | |

(OVER)

| | | | |
|-------------|---|-------------------------|--------------|
| PHOTO | PHOTOGRAPHER Mark McDonough | | DATE 1986 |
| | VIEW SE | NEGATIVE ON FILE D29 | |
| COMPILED BY | NAME Mark McDonough | | DATE 1986 |
| | ORGANIZATION Town of Thompson, Connecticut | | |
| | ADDRESS | | |



20 SUBSEQUENT FIELD EVALUATION:

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

SEE MASTER FORM FOR NORTH GROSVENORDALE MILL HOUSING TYPE F, 1020 ROUTE 12.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SEE MASTER FORM FOR NORTH GROSVENORDALE MILL HOUSING TYPE F, 1020 ROUTE 12.

SOURCES

SEE MASTER FORM FOR NORTH GROSVENORDALE MILL HOUSING TYPE F, 1020 ROUTE 12.

21 THREATS TO BUILDING OR SITE

None known
 Highways
 Vandalism
 Developers
 Other _____

Renewal
 Private
 Deterioration
 Zoning
 Explanation _____