HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES HIST-6 NEW 5/77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION

| 2112 | | | _F0 | RC |)FI | F/C | E U. | SE ON | LY | | |
|------|------|------|-----|----|-----|-----|------|-------|----|---|---|
| 340 | Town | 10.: | | | | | Site | No.: | | V | |
| | UTM | ! | 1:1 | 1 | 1 | ! | : | | 8 | 1 | i |

| UTM | | il | 1 | 1 | ! | | 2 | | i | 1 4 | |
|-------|----|----|---|---|---|--|---|---|---|-----|---|
| QUA | D: | | | | | | | | | | |
| m 1.6 | T | _ | | | - | | | - | - | | , |

| | 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106 | QUAD: |
|---------------|--|------------------------------|
| - | (203) 566-3005 | DISTRICT . IF NR. SPECIFY |
| | 105/34/10// | S NR Actual Potential |
| | 1. BUILDING NAME (Common) (Historic) | • |
| | WATER E. B. | T COUNTY |
| N | THOMPSON | WINDHAM |
| ATI(| 3. STREET AND NUMBER (and or focation) | 105/24 1 10 |
| FIC | 1938 ROUTE 193 (31-3 THOMPSON RD.) | 105/34 1-10 |
| DENTIFICATION | MEUNIER, MARION B., THOMPSON, CT 06277 | Public X Private |
| IDE | 5. USE (Present) (Historic) | |
| | Residence Residence | |
| | ACCESSIBILITY ACCESSIBLE | PLAIN |
| | 70 PUBLIC: Yes No Yes ANO | DATE OF CONSTRUCTION |
| | Greek Revival | c. 1841 |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) Chimney Other | |
| | | .) |
| | X Wood Shingle Asphalt Siding Fieldstone | |
| | | |
| | Board & Batten Stucco Cobblestone | |
| | Aluminum Concrete X Cut. stone Granite for Type: | undation facing |
| | 9. STRUCTURAL SYSTEM | |
| | X Wood frame Post and beam balloon | |
| - 1 | Load bearing masonry Structural iron or steel | |
| | Other (Specify) | |
| - | 10. ROOF (Type) | |
| | X Gable Flat Mansard Monitor sawtoot | h |
| | Gambrel Shed Hip Round (Specify | * |
| PTION | | |
| | (Material) · Roll | |
| DESCR | Wood Shingle Asphalt Tin Slate | X Gable end to the street |
| DE | Asphalt shingle Built up Tile Other (Specify) | Ridge parallel to the street |
| I | 11. NUMBER OF STORIES APPROXIMATE DIMENSIONS | |
| - | 2 1/2 22' x 30' (main part) 12. CONDITION (Structural) (Exterior) | |
| l | Excellent X Good Fair Deteriorated Excellent X Goo | d Fair Deteriorated |
| ı | 13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN | d |
| | ○ On original Moved X Yes No Victorian real | ar porches |
| | 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES Barn X Shed X Garage Other landscape features or building: | |
| | | s (Specity) |
| | Carriage house Shop Garden | |
| | 15. SURROUNDING ENVIRONMENT | |
| | ☐ Open land ☐ land ☐ Residential ☐ Scattered buildings visi | ble from site |
| -1 | Commercial Indus- trial Rural X High building density | |
| | In Thompson Hill, a well-preserved 19th century village | center. |
| | | |

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION 59 South Prospect Street, Hartford, Connecticut 06106

...STORIC RESOURCES INVENTORY FORM For Buildings and Structures

CONTINUATION SHEET #19 WALTER E. BATES Item number: Date:

| for offi | CE USE C | | |
|----------|----------|------|-----------|
| TOWN NO. | | ,517 | re no.: |
| UTM: 18 | 1/_/_/- | /_ | /_/_ |
| QUAD: | , | | |
| DISTRICT | : 5 | NR: | ACTUAL |
| =, | | | POTENTIAL |

tectural movement. The Bates house's trabeated entry, corner pilasters, pedimented peak, and gable-end-to-street orientation were all intended to suggest the massing and construction of a classical Greek temple.