## HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES

HIST-6 NEW 5/77

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106

(203) 566-3005

, COMMECTICUT	00100
/	1 11
122/32	17//

		FU	R	)F	FIC	E U.	SE C	NL	Y			
Town No.:					Site No.:							
MTL		1	!	1	!	!	:	Ī	!	1	!	!
QUAD:												

	(2007 000 0000	122/32/19	7//	DISTRICT	I F NR. SPECIF	Y	
- 1	1. BUILDING NAME (Common)		//	S NR	Actual	Potential	
	1. BUILDING NAME (Common)	1 ***	storic)	T HOUGE			
N.	2. TOWN CITY VILLA		GEORGE DIK	E HOUSE			
	The state of the s	OMPSON			WINDHAM		
Ę	3. STREET AND NUMBER (and/or location)	- Area			<i>i</i>		
CA	103 BRANDY HILL ROAD	(12 0	LEARY K	(25,) 122/32	-17		
DENTIFICATION	4. OWNER(S)				Public		
EN	LEVEILLE, KATHERINE ELOIS, RRI, THO	- I	277	L_	X Private		
	Residence	(His	Residence	4			
	6. CCESSION ATV EXTERIOR VISIBLE FROM PUBLIC ROAD	INTERIOR ACCESSIBLE	IF YES, EX				
	ACCESSIBILITY X Yes No	Yes X No					
	7. STYLE OF BUILDING		1	DATE OF CONSTR	UCTION .		
	Greek Revival			c. 184	5		
	8. MATERIAL(S) (Indicate use or location when appropriate)	- Chimneys	Other				
	Clapboard Asbestos Siding	X Brick	(Specify				
	Wood Shingle Asphalt Siding		7				
	☐ Wood Shingle ☐ Asphalt Siding	X Fieldstone	Foundatio	n			
	Board & Batten Stucco	Cobblestone					
	Aluminum — Comment						
	X Siding Type:	Cut stone Type:					
	9. STRUCTURAL SYSTEM						
	X Wood frame Post and beam	balloon					
	Load bearing masonry	Structural iron				•	
		Sirociardi iron	or steet				
	Other (Specify)			- <del></del>			
	X Gable Fig. Hansard						
	X Gable Flat Mansard	Monitor	sawtooth				
_	Gambrel Shed Hip	Round	Other (Specify)				
٥		Kouna	С (Зресну)				
T I	(Moverial) . Roll .		3				
SCRIPTION	Wood Shingle Asphalt Tin	Slate		X Gable e	nd to the street		
DE	X Asphalt shingle Built up Tile	Other					
}	Asphalt shingle Built up Tile  11. NUMBER OF STORIES APPROXIMATE DIMENSIONS	(Specify)		Ridge p	arallel to the stre	et	
	2 1/2 24' x 29' (main	part)					
ŀ	12. CONDITION (Structural)	(Exterior)		·			
- 1	Excellent X Good Fair Deterior	ated Excellen	t X Good	Fair	Deteriorated		
ſ	13. INTEGRITY (Location) WHEN? (Alteration)  Solve Moved  WHEN? (X) Yes		EXPLAIN		-		
-		s ∐No Lat	er porch				
İ	A RELATED OUTBUILDINGS OR LANDSCAPE FEATURES    X   Born						
1	X Barn Shed Garage Oth	er landscape feature	s or buildings	(Specify)			
	Carriage Shop Garden		*				
t	15 SURROUNDING ENVIRONMENT			*		<u>-</u>	
	Open land Wood- Residential	X Scattered I	ouildings visib	le from site			
	Indus-		#				
-1	Commercial trial X Rural  16 INTERHELATIONSHIP OF BUILDING AND SUFROUNDIN		ing density				
	In a largely rural area of eastern		h a numbo	r of 10+5 ~~~	turn hange	,	
	a rargery rarar area or eastern	THOMPSON WIL	.i. a mumbe.	r or racii cei	reary nouses	O 6	

Explanation\_

Deterioration