

**HISTORIC RESOURCES INVENTORY**  
**BUILDING AND STRUCTURES**  
 HIST-6 NEW 5/77

104

STATE OF CONNECTICUT  
**CONNECTICUT HISTORICAL COMMISSION**  
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106  
 (203) 566-3005

167/88/36/11

| FOR OFFICE USE ONLY                                    |  |
|--|--|
| Town No.:  | Site No.:  |
| UTM  |  |
| QUAD:  |  |
| DISTRICT   | IF NR. SPECIFY   |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

IDENTIFICATION

|  |   |   |                 |
|--|---|---|-----------------|
| 1. BUILDING NAME (Common)  |   | (Historic)                                |                 |
| SWEDE VILLAGE MILL HOUSING   |   | NORTH GROSVENORDALE MILL HOUSING - TYPE A |                 |
| 2. TOWN CITY   | VILLAGE   | COUNTY                                    |                 |
| THOMPSON   | NORTH GROSVENORDALE   | WINDHAM                                   |                 |
| 3. STREET AND NUMBER (and/or location)   |   | 167/88-36                                 |                 |
| 11 HOLMES STREET (8 HOLMES ST.)  |   |   |                 |
| 4. OWNER(S)  |   |   |                 |
| HOULE, LUCIEN R., 45 CUBLES ROAD, VERNON, CT <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private |   |   |                 |
| 5. USE (Present)   |   | (Historic)                                |                 |
| Residence  |   | Residence                                 |                 |
| 6. ACCESSIBILITY TO PUBLIC:  | EXTERIOR VISIBLE FROM PUBLIC ROAD                                   | INTERIOR ACCESSIBLE                       | IF YES, EXPLAIN |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No  | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |   |                 |

DESCRIPTION

|   |   |  |   |
|---|---|--|---|
| 7. STYLE OF BUILDING  |   | DATE OF CONSTRUCTION   |   |
| Mill Housing  |   | c. 1880  |   |
| 8. MATERIAL(S) (Indicate use or location when appropriate)  |   |  |   |
| <input type="checkbox"/> Clapboard  | <input checked="" type="checkbox"/> Asbestos Siding   | <input checked="" type="checkbox"/> Chimney Brick              | <input type="checkbox"/> Other (Specify)  |
| <input type="checkbox"/> Wood Shingle   | <input type="checkbox"/> Asphalt Siding   | <input checked="" type="checkbox"/> Fieldstone Foundation      |   |
| <input type="checkbox"/> Board & Batten   | <input type="checkbox"/> Stucco   | <input type="checkbox"/> Cobblestone                           |   |
| <input type="checkbox"/> Aluminum Siding  | <input type="checkbox"/> Concrete Type:   | <input type="checkbox"/> Cut stone Type:                       |   |
| 9. STRUCTURAL SYSTEM  |   |  |   |
| <input checked="" type="checkbox"/> Wood frame  | <input type="checkbox"/> Post and beam  | <input type="checkbox"/> balloon                               |   |
| <input type="checkbox"/> Load bearing masonry   | <input type="checkbox"/> Structural iron or steel   |  |   |
| <input type="checkbox"/> Other (Specify)  |   |  |   |
| 10. ROOF (Type)   |   |  |   |
| <input checked="" type="checkbox"/> Gable   | <input type="checkbox"/> Flat   | <input type="checkbox"/> Mansard                               | <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth  |
| <input type="checkbox"/> Gambrel  | <input type="checkbox"/> Shed   | <input type="checkbox"/> Hip                                   | <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify)                                   |
| (Material)  |   |  |   |
| <input type="checkbox"/> Wood Shingle   | <input type="checkbox"/> Roll Asphalt   | <input type="checkbox"/> Tin                                   | <input type="checkbox"/> Slate <input type="checkbox"/> Gable end to the street                           |
| <input checked="" type="checkbox"/> Asphalt shingle   | <input type="checkbox"/> Built up   | <input type="checkbox"/> Tile                                  | <input type="checkbox"/> Other (Specify) <input checked="" type="checkbox"/> Ridge parallel to the street |
| 11. NUMBER OF STORIES   | APPROXIMATE DIMENSIONS  |  |   |
| 2 1/2   | 50' x 30'   |  |   |
| 12. CONDITION (Structural)  |   | (Exterior)   |   |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Deteriorated |  |   |
| 13. INTEGRITY (Location)  |   | WHEN ?   | (Alterations) IF YES, EXPLAIN   |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved   |   |  | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No See #17                               |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES  |   |  |   |
| <input type="checkbox"/> Barn   | <input type="checkbox"/> Shed   | <input type="checkbox"/> Garage                                | <input type="checkbox"/> Other landscape features or buildings (Specify)                                  |
| <input type="checkbox"/> Carriage house   | <input type="checkbox"/> Shop   | <input type="checkbox"/> Garden                                |   |
| 15. SURROUNDING ENVIRONMENT   |   |  |   |
| <input type="checkbox"/> Open land <input type="checkbox"/> Wood-land   | <input checked="" type="checkbox"/> Residential   | <input type="checkbox"/> Scattered buildings visible from site |   |
| <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Rural  | <input checked="" type="checkbox"/> High building density   |  |   |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS  |   |  |   |

In a complex of originally identical mill houses just west of the North Grosvenordale Mill.

(OVER)

|             |   |                         |              |
|-------------|---|-------------------------|--------------|
| PHOTO       | PHOTOGRAPHER<br>Mark McDonough                |                         | DATE<br>1986 |
|             | VIEW<br>SW                                    | NEGATIVE ON FILE<br>B34 |              |
| COMPILED BY | NAME<br>Mark McDonough                        |                         | DATE<br>1986 |
|             | ORGANIZATION<br>Town of Thompson, Connecticut |                         |              |
|             | ADDRESS                                       |                         |              |



20 SUBSEQUENT FIELD EVALUATION:

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

SEE MASTER FORM, NORTH GROSVENORDALE MILL HOUSING TYPE A,  
4 HOLMES STREET

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SEE MASTER FORM, NORTH GROSVENORDALE MILL HOUSING TYPE A, 4 HOLMES STREET.

SIGNIFICANCE

SOURCES

SEE MASTER FORM, NORTH GROSVENORDALE MILL HOUSING TYPE A, 4 HOLMES STREET.

21 THREATS TO BUILDING OR SITE

- None known
- Highways
- Vandalism
- Developers
- Other \_\_\_\_\_
- Renewal
- Private
- Deterioration
- Zoning
- Explanaton \_\_\_\_\_