

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5/77

093

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

167/88/38//

FOR OFFICE USE ONLY	
Town No.:	Site No.:
UTM	
QUAD:	
DISTRICT	IF NR. SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION	1. BUILDING NAME (Common) (Historic) SWEDE VILLAGE MILL HOUSING		NORTH GROSVENORDALE MILL HOUSING - TYPE A		
	2. TOWN CITY THOMPSON		VILLAGE NORTH GROSVENORDALE	COUNTY WINDHAM	
	3. STREET AND NUMBER (and/or location) 32 FLORAL AVENUE (14 FLORAL AVE.)		167/88-38		
	4. OWNER(S) BERGER, NORMAND P., N. GROSVENORDALE, CT 06255		<input type="checkbox"/> Public <input checked="" type="checkbox"/> Private		
	5. USE (Present) Residence		(Historic) Residence		
	6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		EXTERIOR VISIBLE FROM PUBLIC ROAD <input type="checkbox"/> Yes <input type="checkbox"/> No		
DESCRIPTION	7. STYLE OF BUILDING Mill Housing		DATE OF CONSTRUCTION c. 1880		
	8. MATERIAL(S) (Indicate use or location when appropriate)		<input checked="" type="checkbox"/> Chimneys <input type="checkbox"/> Other (Specify)		
	<input checked="" type="checkbox"/> Wood Shingle		<input checked="" type="checkbox"/> Fieldstone Foundation		
	<input type="checkbox"/> Board & Batten		<input type="checkbox"/> Cobblestone		
	<input type="checkbox"/> Aluminum Siding		<input type="checkbox"/> Concrete Type: _____		
	<input type="checkbox"/> Asphalt Siding		<input type="checkbox"/> Cut stone Type: _____		
	9. STRUCTURAL SYSTEM		<input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> balloon		
	<input type="checkbox"/> Load bearing masonry		<input type="checkbox"/> Structural iron or steel		
	<input type="checkbox"/> Other (Specify) _____				
	10. ROOF (Type)		<input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth		
<input type="checkbox"/> Gambrel		<input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____			
(Material)		<input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Gable end to the street			
<input checked="" type="checkbox"/> Asphalt shingle		<input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Ridge parallel to the street			
11. NUMBER OF STORIES 2 1/2		APPROXIMATE DIMENSIONS 50' x 30'			
12. CONDITION (Structural)		(Exterior)			
<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated		<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated			
13. INTEGRITY (Location)		WHEN ? (Alterations) IF YES, EXPLAIN			
<input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No See #17			
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES					
<input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage		<input type="checkbox"/> Other landscape features or buildings (Specify)			
<input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden					
15. SURROUNDING ENVIRONMENT					
<input type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential		<input type="checkbox"/> Scattered buildings visible from site			
<input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Rural		<input checked="" type="checkbox"/> High building density			
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS		In a complex of originally identical mill housing just west of the North Grosvenordale Mill.			

(OVER)

PHOTO	PHOTOGRAPHER Mark McDonough		DATE 1986
	VIEW NW	NEGATIVE ON FILE B27	
COMPILED BY	NAME Mark McDonough		DATE 1986
	ORGANIZATION Town of Thompson, Connecticut		
	ADDRESS		



20 SUBSEQUENT FIELD EVALUATION:

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

SEE MASTER FORM, NORTH GROSVENORDALE MILL HOUSING TYPE A, 4 HOLMES STREET.

DESCRIPTION (Continued)

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SEE MASTER FORM, NORTH GROSVENORDALE MILL HOUSING TYPE A, 4 HOLMES STREET.

SIGNIFICANCE

SEE MASTER FORM, NORTH GROSVENORDALE MILL HOUSING TYPE A, 4 HOLMES STREET.

SOURCES

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterioration Zoning Explanation _____