## HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES

HIST-6 NEW 5/77

## STATE OF CONNECTICUT CONNECTICUT HISTORICAL COMMISSION

59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106

Site No.:	
1!1	1
c	CIFY

(203) 566-3005 Potential 1. BUILDING NAME (Common) (Historic) ERNEST PRINCE HOUSE 2. TOWN CITY VILLAGE COUNTY THOMPSON DENTIFICATION WINDHAM NORTH GROSVENORDALE 3. STREET AND NUMBER (and/or locarion) MAIN ST. 169/91-28 212 MAIN STREET DESILETS, LUCILLE, N. GROSVENORDALE, CT X Private Public 06255 5. USE (Present) (Historic) Residence Residence IF YES, EXPLAIN EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE ACCESSIBILITY X Yes X No TO PUBLIC: STYLE OF BUILDING DATE OF CONSTRUCTION c. 1938 Bungalow 8. MATERIAL(S) (Indicate use or location when appropriate) Chimney Other X Brick Clapboard Asbestos Siding (Specify) Porch, Piers X Wood Shingle Fieldstone Asphalt Siding Board & Batten Stucco Foundation Cobblestone Aluminum Concrete Siding Type: Type: 9. STRUCTURAL SYSTEM X Wood frame Post and beam Load bearing masonry Structural iron or steel Other (Specify) 10. ROOF (Type) X Gable Mansard sawtooth Other Gambrel (Specify DESCRIPTION (Material) Roll X Wood Shingle Asphalt Gable end to the street Slate Other Asphalt shingle Built up Ridge parallel to the street Tile Specify 11. NUMBER OF STORIES APPROXIMATE DIMENSIONS 1 1/2 28' x 27' 12. CONDITION (Structural) (Exterior) Excellent X Good X Good Fair Deteriorated Excellent Deteriorated 13. INTEGRITY (Location) (Alterations) On original X Yes Modern storm sash Moved site 14 RELATED OUTBUILDINGS OF FATURES Barn Shed Garage Other landscape features or buildings (Specify) Carriage Shop Garden house SURROUNDING ENVIRONMENT Wood-X Residential Open land Scattered buildings visible from site land Indus-X High building density INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
Just across from Victorian St. Joseph's Roman Catholic Church. One of a few 20th century buildings in this well preserved 19th century mill village. (OVER)

-	PHOTOGRAPHER	DATE				
TO	Mark McDonough	1986	A STATE OF THE STA		1	
PHOTO	NE NEGATIVE O	N FILE				
BY	NAME	DATE				
ED B	Mark McDonough	1986				
MPILE	Town of Thompson, Connect:	icut			1	
OMF	ADDRESS				7	
30.3	SUBSEQUENT FIELD EVALUATION.				1	
20 .			land the state of			
	Two-hay facade Front fac	ILDING OR SITE (interi	or und/or exterior)	s to right, entry under screened-	:-	
	porch to left. Porch has	brick piers, b	attered wood c	olumns, molded cornice on bracket	ın s.	
(Pa	Sash generally four harrow	vertical pane	s over one. C	verhanging eaves on kneebraces.		
ESCRIPTION (Continued)	Side elevations have semi-	circular attic	louvers.			
رد				9		
O						
T d li	•					
SCR					z=	
DE		. •				
	-					
	IB ARCHITECT		BUILDER			
	19 HISTORICAL OR ARCHITECTURAL T	MPORTANCE			Yes	
	This house was built in 19 nearby cotton textile mill	937 by Ernest P Ls.	rince, who wor	ked in the Grosvenor Dale Company	's	
П	Historically, it is significantly 20th century.	ficant as a goo	d example of s	simple working class housing from	the ·	
SIGNIFICANCI	It is architecturally significant as a good example of the Bungalow style. The Bungalow style, an outgrowth of the English Arts and Crafts Movement, honored the ideal traditional hand craftsmanship through the extensive use of picturesque detailing. The battered porch posts, overhanging eaves, and unusual sash are all typical Bungalow features.					
S	-					
- 1						
				•		
				·		
			,			
	1949 Putnam Directory					
ES.	Thompson Land Records 42:	:181 (1937)				
SOURCES						
Sol	v .				4.	
			-		*	
-	HREATS TO BUILDING OR SITE	· · · · · · · · · · · · · · · · · · ·	<u> </u>			
△ N	ane known Highways	Vandalism	Developers	Other		