

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5/77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

154


169/92/10//

FOR OFFICE USE ONLY	
Town No.:	Site No.:
UTM	
QUAD:	
DISTRICT	IF NR. SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION	1. BUILDING NAME (Common) <i>(Historic)</i> THREE ROWS MILL HOUSING		NORTH GROSVENORDALE MILL HOUSING - TYPE C		
	2. TOWN CITY THOMPSON		VILLAGE NORTH GROSVENORDALE	COUNTY WINDHAM	
	3. STREET AND NUMBER (and/or location) 49 MARSHALL STREET (24 MARSHALL ST.)		169/92-10		
	4. OWNER(S) KURTZ, JOHN R. & NANCY C., N. GROSVENORDALE, CT 06255		<input type="checkbox"/> Public <input checked="" type="checkbox"/> Private		
	5. USE (Present) Residence		<i>(Historic)</i> Residence		
	6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		EXTERIOR VISIBLE FROM PUBLIC ROAD <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		INTERIOR ACCESSIBLE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
DESCRIPTION	7. STYLE OF BUILDING Mill Housing		DATE OF CONSTRUCTION c. 1870		
	8. MATERIAL(S) (Indicate use or location when appropriate)				
	<input type="checkbox"/> Clapboard		<input type="checkbox"/> Asbestos Siding		<input checked="" type="checkbox"/> Chimneys <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Other (Specify)
	<input type="checkbox"/> Wood Shingle		<input type="checkbox"/> Asphalt Siding		<input checked="" type="checkbox"/> Fieldstone Foundation
	<input type="checkbox"/> Board & Batten		<input type="checkbox"/> Stucco		<input type="checkbox"/> Cobblestone
	<input checked="" type="checkbox"/> Aluminum Siding		<input type="checkbox"/> Concrete Type: _____		<input type="checkbox"/> Cut stone Type: _____
	9. STRUCTURAL SYSTEM				
	<input checked="" type="checkbox"/> Wood frame		<input type="checkbox"/> Post and beam		<input type="checkbox"/> balloon
	<input type="checkbox"/> Load bearing masonry		<input type="checkbox"/> Structural iron or steel		
	<input type="checkbox"/> Other (Specify) _____				
10. ROOF (Type)					
<input checked="" type="checkbox"/> Gable		<input type="checkbox"/> Flat		<input type="checkbox"/> Mansard	
<input type="checkbox"/> Gambrel		<input type="checkbox"/> Shed		<input type="checkbox"/> Hip	
<input type="checkbox"/> Wood Shingle		<input type="checkbox"/> Roll Asphalt		<input type="checkbox"/> Tin	
<input checked="" type="checkbox"/> Asphalt shingle		<input type="checkbox"/> Built up		<input type="checkbox"/> Tile	
<input type="checkbox"/> Gable end to the street		<input checked="" type="checkbox"/> Ridge parallel to the street			
11. NUMBER OF STORIES 2 1/2		APPROXIMATE DIMENSIONS 50' x 32'			
12. CONDITION (Structural) <i>(Exterior)</i>					
<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good		<input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated		<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good	
13. INTEGRITY (Location)		WHEN ?		(Alterations)	
<input checked="" type="checkbox"/> On original site		<input type="checkbox"/> Moved		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES		IF YES, EXPLAIN			
<input type="checkbox"/> Barn		<input type="checkbox"/> Shed		<input type="checkbox"/> Garage	
<input type="checkbox"/> Carriage house		<input type="checkbox"/> Shop		<input type="checkbox"/> Garden	
15. SURROUNDING ENVIRONMENT					
<input type="checkbox"/> Open land		<input type="checkbox"/> Wood-land		<input checked="" type="checkbox"/> Residential	
<input type="checkbox"/> Commercial		<input type="checkbox"/> Indus-trial		<input type="checkbox"/> Rural	
<input checked="" type="checkbox"/> High building density		<input type="checkbox"/> Scattered buildings visible from site			
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS					
In three rows of highly similar mill housing southeast of the North Grosvenordale mill.					

(OVER)

PHOTO	PHOTOGRAPHER Mark McDonough	DATE 1986
	VIEW SW	NEGATIVE ON FILE B5
COMPILED BY	NAME Mark McDonough	DATE 1986
	ORGANIZATION Town of Thompson, Connecticut	
	ADDRESS	



20 SUBSEQUENT FIELD EVALUATION:

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

SEE MASTER FORM FOR NORTH GROSVENORDALE MILL HOUSING, TYPE C - 27 CENTRAL STREET.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

SEE MASTER FORM FOR NORTH GROSVENORDALE MILL HOUSING, TYPE C - 27 CENTRAL STREET.

SOURCES

SEE MASTER FORM FOR NORTH GROSVENORDALE MILL HOUSING, TYPE C - 27 CENTRAL STREET.

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterioration Zoning Explanation _____