HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES HIST-6 NEW 5/77

STATE OF CONNECTICUT CONNECTICUT HISTORICAL COMMISSION

155	FOR OFFICE USE ONLY					
105	Town No.:	Site No.:				
or and a second	UTM !	1111111				
JT 06106	QUAD:					
2/11/1	DISTRICT	F NR. SPECIFY				

	59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106 (203) 566-3005		QUAD:						
	(203) 566-30	1005	DISTRICT , IF NR. SPECIFY						
		169/92/11//	S NR Actual Potential						
	1. BUILDING NAME (Common)	(Historic)	VENORDALE MILL HOUSING - TYPE C						
	THREE ROW MILL HOUSING		VENORDALE MILL HOUSING - 11PE C						
7	2. TOWN CITY THOMPSON	NORTH GROSVENORDALE	WINDHAM						
0	3. STREET AND NUMBER (and/or locatton)	HORIT GROSVENOIGHE	WINDHAM						
CAJ		1 ARSHALL ST.)	169/92-11						
IFI.	4. OWNERIS)								
DENTIFICATION	BEAULIEU, LUCIEN J. SR. & LINDA L., N. GROSVENORDALE, CT 06255								
IDE	5. USE (Present)	(Historic)							
	Residence	Residence							
	ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC I		PLAIN						
	7. STYLE OF BUILDING	Yes ANO	DATE OF CONSTRUCTION						
	Mill Housing		c. 1870						
	8. MATERIAL(S) (Indicate use or location when app	propriate)							
	Clapboard Asbestos Siding	Chimney Other (Specify)							
	☐ Wood Shingle ☐ Asphalt Siding	X Fieldstone Foundation	n						
	Board & Batten Stucco	<u> </u>							
		Cobblestone							
	Aluminum Concrete Type:	Cut stone Type:							
	9. STRUCTURAL SYSTEM								
	X Wood frame Post and beam	balloon							
	Load bearing masonry	Structural iron or steel							
	Other (Specify)		,						
	10. ROOF (Type)								
	X Gable Flot Man	nsard Monitor sawtooth							
	Gambrel Shed Hip	Other Other							
RIPTION	Gambrel Shed Hip	Round (Specify)							
PT	(Material)	4							
CR	Wood Shingle Roll Asphalt Tin	Slate	Gable end to the street						
DESCI		Other							
	XI Aspholt shingle Built up Tile		X Ridge parallel to the street						
İ	11 NUMBER OF STORIES APPROXIMATE DIMEN 2 1/2 50' x 32'	SIONS							
}	12 CONDITION (Structural) (Exterior)								
	Excellent X Good Fair	Deteriorated Excellent X Good	Fair Deteriorated						
ı	13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN								
	X On original Moved X Yes No See #17								
	14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES								
	Barn Shed Garage Other landscape features or buildings (Specify)								
	Carriage Shop Garden								
ŀ	house Shop Garden Surrounding Environment								
	Open land Wood X Residential	Scattered buildings visib	le from site						
	☐ ☐ Indus- ☐								
	Commercial I Rural	X High building density							
	In three rows of very similar		t of the North Grosvenordale						
l	mill.	I MILL HOUSING JUSC SOUCHEAST	C OI CHE HOLEH GLOSVEHOLUALE						
		¥	(OVER)						
1			10,500						

-	PHOTOGRAPHER			**** * *******************************			
0		DATE			1		
PHOTO	Mark McDonough	1986			T		
ā	SW B6	-			*		
<u></u>	NAME	DATE					
D 8Y	Mark McDonough	1986	11		H.		
LED	ORGANIZATION						
COMPIL	Town of Thompson, Connecticut	T.					
00					VA		
20 5	SUBSEQUENT FIELD EVALUATION'.				- - 4		
			_ '/////		2 500 7 43		
					. 5		
		1					
. 7	17 OTHER NOTABLE FEATURES OF BUILDI	NG OR SITE (Interior III	nd/or exterior)				
		and a second and a second as	in the exterior,				
	SEE MASTER FORM FOR NORTH C	POSTENOPONTE N	ATTI HOUSTNO	G, TYPE C - 27 CENTRAL STREET.			
DESCRIPTION (Continued)	in the state of th	SKOOVENOIDALL I	IIII HOODING	s, TIPE C - 27 CENTRAL STREET.			
tin					•		
Col							
Z							
1							
RIP							
ESC	*						
					7		
7	18 ARCHITECT		BUILDER				
	IA WISTAGLE ALL OF A DATE OF WALL THE						
19 HISTORICAL OR ARCHITECTURAL IMPORTANCE							
1	SEE MASTER FORM FOR NORTH	GROSVENORDALE	MILL HOUSI	NG, TYPE C - 27 CENTRAL STREET	· .		
ш							
SIGNIFICANCE							
2							
F							
5							
-							
	•						
+							
5							
SEE MASTER FORM FOR NORTH GROSVENORDALE MILL HOUSING, TYPE C - 27 CENTRAL ST							
5							
SOURCES							
				•	å.		
21 +	HREATS TO BUILDING OR SITE				å		
21 +		ndalism []	Developers	Other	1		
X N	one known Highways Van		Developers Zoning	Other	1		