HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES HIST-6 NEW 5/77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION

14/	FOR OFFICE USE ONLY				
16	Town No.:	s	ite No.:		
	UTM !	1 : :	1111		

	59 SOUTH PROSPECT STREET, HART	FORD, CONNECTICU	T 06106	QUAD:				
	(203) 566-30	169	193/4//	DISTRICT IF NR. SP				
IDENTIFICATION	1. BUILDING NAME (Common)		(Historic)	S NR Actua	Potential			
	GREEK VILLAGE MILL HOUSING	*	NORTH GRO	SVENORDALE MILL HOUS	ING - TYPE D			
	2. TOWN CITY THOMPSON 3. STREET AND NUMBER (and/or location)	NORTH GROSVE	NORDALE	COUNTY WINDHAM				
	22 MARKET LANE () 1 MARKE	T LANE)		169/93-4				
	NIZAMOFF, VICTOR, N. GROSVENO	RDALE, CT 0625		Public	X Private			
	Residence		(Mistorie) Residen	ce				
	ACCESSIBILITY EXTERIOR VIBLE FROM PUBLIC R TO PUBLIC: XYes No		No IF YES, EX	PLAIN				
	7. STYLE OF BUILDING Mill Housing			date of construction after 1872				
	8. MATERIAL(S) (Indicate use or location when appr Clapboard Asbestos Siding	Chimn X Brick	eys Other	·)				
	Wood Shingle X Asphalt Siding	X Fieldsto	ne Foundation	on	•			
	Board & Batten Stucco	Cobblest	one					
	Aluminum Concrete Siding Type:	Cut ston	e					
	9. STRUCTURAL SYSTEM X Wood frame Post and beam	balloon	я					
	Load bearing masonry	Structura	liron or steel					
	Other (Specify)							
	∑ Gable Flot Mans	sard Monitor	sawtooth	1				
PTION	Gambrel Shed Hip	Round	Other (Specify)				
DESCRIPT	(Material) Wood Shingle Roll Asphalt Tin	Slate		X Gable end to the str	eet .			
DE	X Asphalt shingle Built up Tile	Other (Specify)		Ridge parallel to the	street			
	11. NUMBER OF STORIES APPROXIMATE DIMENS 2 1/2 32' x 120'	IONS		,	_			
	12. CONDITION (Structural) Excellent X Good Fair [Deteriorated Exc	ellent Good	d X Fair Deteriorate	.1			
	13. INTEGRITY (Location) WHEN?	TO DO SE A SECULIAR PROPERTY OF THE PARTY OF	YES, EXPLAIN See #17	Deteriorate				
	14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES Barn Shed Garage Other landscape features or buildings (Specify)							
	Carriage Shop Garden							
	Open land Wood- X Residential	Scatte	ered buildings visib	ole from site	,			
F	Commercial Indus- Rural 16 INTERRELATIONSHIP OF BUILDING AND SURR	X High	building density					
	One of four similar mill houses just east of Three Rows mill housing, southeast of							
	the North Grosvenordale mill			-				
					(OVER)			

	PHOTOGRAPHER	DATE	,		
2	Mark McDonough	1986	ľ		
РНОТО	VIEW NEGATIVE				
•	NE B21				
BY	NAME	DATE			
ED E	Mark McDonough	1986			***
1.		rticut	4		L. State
COMPIL	Town of Thompson, Connec	, creat			
					0.10
20 S	UBSEQUENT FIELD EVALUATION'				R OFF
-					
l	17 OTHER NOTABLE FEATURES OF	BUILDING OR SITE (Interi	or and/or exterior)		
	GER MAGEER BORN BOR WORK	. anagrmnoppata	MILL HOUGING	MADIED A MADIEM CAND	
P	SEE MASTER FORM FOR NORT	H GROSVENORDALE	MILL HOUSING -	TIPE D, 4 MARKET LANE.	
DESCRIPTION (Continued)				·	
on					
2				•	
<u>0</u>					
al P					
SCI					
9					
	IB ARCHITECT		BUILDER		.,
	19 HISTORICAL OR ARCHITECTURA	LIMPORTANCE			
	ann Magner Horn Hor North		MITT HOHEING IN	WINT D A MADVEM LAME	
	SEE MASTER FORM FOR NOR!	TH GROSVENORDALE	MILL HOUSING IN	YPE D, 4 MARKET LANE.	
U			*		
V					
SIGNIFICANCE					
SIG					25
		,		₹	
	<u> </u>				
-					
S	SEE MASTER FORM FOR NOR	TH GROSVENORDALE	MILL HOUSING TY	YPE D, 4 MARKET LANE.	
SOURCES					
00					
"			œ.		
21	HREATS TO BUILDING OR SITE	· · · · · · · · · · · · · · · · · · ·			
	lone known Highways	Vandalism [Developers	Other	
		<u></u>	_		
	Renewal Private	Deterioration	Zoning	Explanation	