HISTORIC RESOURCES INVENTORY FOR OFFICE USE ONLY **BUILDING AND STRUCTURES** Town No .: Site No.: HIST-6 NEW 5/77 STATE OF CONNECTICUT UTM CONNECTICUT HISTORICAL COMMISSION 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106 QUAD: (203) 566-3005 DISTRICT IF NR SPECIE S NR Actual Potential 1. BUILDING NAME (Common) Historic 2. TOWN CITY FABYAN WINDHAM DENTIFICATION THOMPSON 3. STREET AND NUMBER (and/or location) 158 FABYAN-WOODSTOCK ROAD 601 FABYAN 17/84-33 4. OWNER(S) X Private BENO, HELEN, FABYAN, CT Public 5. USE (Present) (Historic) Residence Residence (Mill Housing) EXTERIOR VISIBLE FROM PUBLIC ROAD IF YES. EXPLAIN INTERIOR ACCESSIBLE ACCESSIBILITY XINO X Yes TO PUBLIC: No Yes STYLE OF BUILDING DATE OF CONSTRUCTION Vernacular 19th century 8. MATERIAL(S) (Indicate use or location when appropriate) Chimney Other X Brick Clapboard X Asbestos Siding (Specify) -Demolished 1994 Foundation Wood Shingle Asphalt Siding Fieldstone Board & Batten Cobblestone Stucco Aluminum Concrete Cut stone Siding Type: Type: 9. STRUCTURAL SYSTEM X Wood frame Post and beam balloon Load bearing masonry Structural iron or steel Other (Specify) 10. ROOF (Type) X Gable Flat Mansard Monitor sawtooth Other Gambrel (Specify, DESCRIPTION (Material) Roll Gable end to the street Asphalt Wood Shingle Other Ridge parallel to the street Built up Specifyl Xi Asphalt shingle 11. NUMBER OF STORIES APPROXIMATE DIMENSIONS 32' x 16' 12. CONDITION (Structural (Exterior) X Fair X Fair Excellent __ Good Deteriorated Excellent Deteriorated Good 13. INTEGRITY (Location) WHEN 7 IF YES, EXPLAIN (Alterations) X On original site XYes Siding, later porch Moved 14 RELATED OUTBUILDINGS OR FATURES

Barn Shed Garage

land

Other landscape features or buildings (Specify)

X High building density

Scattered buildings visible from site

Carriage Shop Garden house

15. SURROUNDING ENVIRONMENT Wood-X Residential Open land

Commercial

16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS In a small 19th century mill village.

_	I Buotogo a com	٠ .			in the second	
РНОТО	Mark McDonough	1986	100.0			
	VIEW NEGATIVE ON FILE			======================================	£	<u>~</u>
۵.	_ E . H3					
BY	Mark McDonough	1986	1		15	
ED	ORGANIZATION	1986				
	Town of Thompson, Connecticut		New -	Page 6 Maria Maria Maria Maria		
COMPIL	ADDRESS					
	SUBSEQUENT FIELD EVALUATION .		7			
20	SUBSEQUENT FIELD EVALUATION.					
				'EU		44 46
					A A STATE OF THE PARTY OF THE P	
-	17 OTHER NOTABLE FEATURES OF BUILDING	OR SITE (Interior	: exterior)			
	Four-bay over five-bay facade	. irregul	spaced.	Entry in third b	ay; wood door	r has
۵, ا	one large light over panels. porch; porch entry offset lef	Sash gen	y 2-over	-2. Full width o	ne story glas	ssed-in
300	shed-roofed rear wing.	c. Plain	ed cornice	e. Twin brick ch	imneys. One	story
ESCRIPTION (Continued)						
0)	*					
101				,		
RIP						
ESC			ar .			
D	•					
	18 ARCHITECT					ĺ
NCE	a and a contract		BUILDER			
	19 HISTORICAL OR ARCHITECTURAL IMPORTAN		<u> </u>			
	This simple dwelling was built in the man 19th century, almost certainly as worker					
	housing for the nearby woolen mills (no nger extant). Fabyan's woolen mills (the village was known as New Boston during to the 19th century) have a rather ill					
	starred history dating back t	on during o 1829. Ed	an of the a	19th century) hav	e a rather il	.l
	sea shortly after purchasing	property f:	a satinet	mill. Several f	ires and floo	n ac ods
V	razed subsequent mills; the f	inal blow w	dealt by	the huge flood o	f 1955 Thic	•
SIGNIFICAN	building was owned for many y and eventually went bankrupt.	ears by that In 1867	was being	nily, who bought	the mills in	1865
					-	
	Architecturally, the building worker housing of this second-	tier mill	prain, sr	lowing the lack o	f pretention	in the
l						9.
SOURCES	1867 Atlas					
	Thompson Land Records 33:214 (1908)					
001	,					
5						
	HREATS TO BUILDING OR SITE					1
X	one known Highways Vandalis	sm .	Developers	Other		
, F	enewal Private Deterior	atten 🗆	Zoning	Explanation		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~