₩ISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES HIST-6 NEW 5/77

FOR OFFICE USE ONLY Town No.: Site No.:

TM '	1:	1 ! !	!	!	1
			لنا	L <u>i</u>	L

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106

UTM				!	
QUAD:					
DISTR	ICT NR	IF NR. S			otential

	(203) 566-3005							
	23/105/24// DISTRICT IF NR. SPECIFY S NR Actual Potential							
====	1. BUILDING NAME (Common) S NR Actual Potential							
DENTIFICATION	JOSEPH J. GREEN HOUSE							
	2. TOWN CITY VILLAGE COUNTY							
	THOMPSON WEST THOMPSON WINDHAM							
	3. STREET AND NUMBER (and/or location) RAVENNELL ROAD (no street number) (98 PAUSAIS, 5 Page 23/105-24							
E	RAVENNELL ROAD (no street number) (98 RAVENELLE Ro.) 23/105-24							
F	RAVENELLE, NORMAND A. & BRONISLAWA, RR1. N. GROSVENORDALE, CT 06255 Public Private							
0	5. USE (Present) (Historic)							
	Residence Residence							
	ACCESSIBILITY EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN							
	TO PUBLIC: X Yes No Yes X No							
	Vernacular/Federal C. 1820							
	8. MATERIAL (S) (Individe use or location when approximate)							
	Clapboard Ashastas Sidias X of Illiney Other							
	Asbestos Stating (Specify)							
	Wood Shingle X Asphalt Siding X Fieldstone Foundation							
2 14								
	Board & Batten Stucco Cobblestone							
	Aluminum Concrete Cut stone Type:							
	9. STRUCTURAL SYSTEM							
	X Wood frame Post and beam balloon							
	Load bearing masonry Structural iron or steel							
	Other (Specify)							
	10. ROOF (Type)							
	☐ Gable ☐ Flat ☐ Mansard ☐ Monitor ☐ sawtooth							
	Other							
	Gambrel Shed Hip Round (Specify)							
CRIPTION	[†] Material)							
CRI	Wood Shingle Roll Slate Gable end to the street							
DES	Other Dother							
	X Asphalt shingle Built up Tile (Specify) X Ridge parallel to the street							
	11. NUMBER OF STORIES APPROXIMATE DIMENSIONS 2 1/2 41' x 29'							
	12 CONDITION (Structural) (Exterior)							
	Excellent X Good Fair Deteriorated Excellent X Good Fair Deteriorated							
Ì	13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN							
	On original Moved X Yes No Later siding, sun porch							
	14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES							
1	Barn Shed X Garage X Other landscape features or buildings (Specify)							
	Dry-stone retaining wall house Shop Garden							
+	15 SURROUNDING ENVIRONMENT							
-	Open land I Wood- X Residential X Scattered buildings visible from site							
7	Commercial trial X Rural High building density							
	In a semi-rural area of western Thompson; most surrounding houses are recent.							
-	and the second and sec							
- 1	·							

Zoning

Deterioration

Explanation_

Renewal

PHOTOGRAPHER