HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES HIST-6 NEW 5/77

STATE OF CONNECTICUT

210	FOR OFFICE USE ONLY											
218	Town No.	:				Site	No.:					1
	UTM !	T	:	1	-	1	1	1	1	1	1	!
JT 06106	QUAD:				-				ť			

(OVER)

	CONNECTICUT HISTORICAL COMMISSION	UTM :										
	59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106	QUAD:										
	(203) 566-3005	DISTRICT IF NR. SPECIFY										
	1. BUILDING NAME (Common) (Historic)	S NR Actual Potential										
	1. BUILDING NAME (Common) (Historic) HERBERT	E. REYNOLDS HOUSE										
DENTIFICATION	THOMPSON THOMPSON	COUNTY WINDHAM										
	1682 ROUTE 193 (463 THOMPSON RD.)	103/31-3A										
	A. OWNER(S) AUGER, ALBERT R. & JEAN C., RR #1, THOMPSON, CT 06277	Public A Private										
0	5. USE (Present) (Historic) Residence Residence	e										
	ACCESSIBILITY X Yes No INTERIOR ACCESSIBLE IF YES, E											
	7. STYLE OF BUILDING Bungalow	DATE OF CONSTRUCTION C. 1930										
	8. MATERIALIS) (Indicate use or location when appropriate)	. 1550										
	O Other	fy)										
	X Wood Shingle Asphalt Siding X Fieldstone Foundati	on										
	Board & Batten Stucco Cobblestone											
	Aluminum Concrete Type: Cut stone Type:											
	■ Wood frame ■ Post and beam ■ balloon											
	Load bearing masonry Structural iron or steel											
	Other (Specify)	4										
Z.	Gable Flat Mansard Monitor sawtoo	th										
	Gambrel Shed X Hip Round Other (Special	(y)										
PTIC	(Material)											
DESCRIPTION	Wood Shingle Roll Tin Slate	X Gable end to the street										
DE	Asphalt shingle Built up Tile (Specify)	Ridge parallel to the street										
	1 1/2 26' x 33'											
1	12. CONDITION (Structural) (Exterior)											
ļ	Excellent X Good Fair Deteriorated Excellent X Go	od Fair Deteriorated										
l	Om original Tu Sone new sa	sh										
ŀ	14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES	,										
	Barn Shed Garage Other landscape features or buildings (Specify)											
	Carriage Shop Garden											
İ	15. SURROUNDING ENVIRONMENT											
	Open land Wood* X Residential Scattered buildings vis	sible from site										
	Commercial X Indus- X Rural High building density 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS											
	One of very few well-preserved bugalows in Thompson;	in a mixed residential/rural/										
	industrial area.											