## HISTORIC RESOURCES INVENTORY FOR OFFICE USE ONLY BUILDING AND STRUCTURES HIST-6 NEW 5/77 Town No .: Site No .: STATE OF CONNECTICUT UTM CONNECTICUT HISTORICAL COMMISSION 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106 QUAD: (203) 566-3005 DISTRICT IF NR. SPECIFY NR Actual Potential 1. BUILDING NAME (Common) 2. TOWN CIT THOMPSON WINDHAM THOMPSON 3. STREET AND NUMBER (and/or (ocation) 1921 ROUTE 193 105/38-10 326 THOMPSON CONGREGATIONAL CHURCH OF THOMPSON, INC. X Private Public 5. USE (Present) (Historic) Residence Residence EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE YES, EXPLAIN ACCESSIBILITY XYes TO PUBLIC: XNo 7. STYLE OF BUILDING DATE OF CONSTRUCTION Victorian Vernacular c. 1880 8. MATERIAL(S) (Indicate use or location when appropriate) X Clapboard Other X Brick Asbestos Siding (Specify) Wood Shingle Asphalt Siding Fieldstone Board & Batten Stucco Cobblestone Aluminum Concrete Cut stone Siding Type: 9. STRUCTURAL SYSTEM Wood frame Post and beam balloon Load bearing masonry Structural iron or steel Other (Specify) 10. ROOF (Type) X Gable Flot Mansard Monitor sawtooth Other Gambrel DESCRIPTION Round (Spicify (Material) Roll Wood Shingle Asphalt Slate Gable end to the street Other Asphalt shingle Built up (Specify) Ridge parallel to the street 11. NUMBER OF STORIES APPROXIMATE DIMENSIONS 2 1/2 24' x 32' 12. CONDITION (Structural) X Good Excellent Deteriorated Excellent X Good Deteriorated 13. INTEGRITY (Los alion) (Alterations) IF YES, EXPLAIN On original XYes c. 1915 porch Moved site BUIL DINGS OF X Garage Barn Shed Other landscape features or buildings (Specify) Carriage house Garden 15. SURROUNDING ENVIRONMENT Wood-Open land Residential Scattered buildings visible from site land X High building density trial INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS In Thompson Hill, an extensive and well preserved 19th century village center.

Deterioration

Zonina

Explanation