

327

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
(203) 566-3005

105/40/15/1

FOR OFFICE USE ONLY	
Town No.:	Site No.:
UTM	
QUAD:	
DISTRICT	IF NR. SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. BUILDING NAME (Common)		(Historic)	
THOMPSON		TALCOTT CROSBY HOUSE (2)	
2. TOWN CITY	VILLAGE	COUNTY	
THOMPSON	THOMPSON	WINDHAM	
3. STREET AND NUMBER (and/or location)			
1855 ROUTE 193 (362 THOMPSON Rd.)		105/40-15	
4. OWNER(S)			
O'NEILL, ANN M. & JOSEPH B., BOX 62, THOMPSON, CT 06277			
5. USE (Present)			
Residence		(Historic) Residence	
6. ACCESSIBILITY TO PUBLIC:			
EXTERIOR VISIBLE FROM PUBLIC ROAD		INTERIOR ACCESSIBLE	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

7. STYLE OF BUILDING		DATE OF CONSTRUCTION	
Queen Anne		c. 1887 (remodelled); c. 1827	
8. MATERIAL(S) (Indicate use or location when appropriate)			
<input checked="" type="checkbox"/> Clapboard	<input type="checkbox"/> Asbestos Siding	<input type="checkbox"/> Brick	<input type="checkbox"/> Other (Specify)
<input checked="" type="checkbox"/> Wood Shingle	<input type="checkbox"/> Asphalt Siding	<input checked="" type="checkbox"/> Fieldstone	Foundation
<input type="checkbox"/> Board & Batten	<input type="checkbox"/> Stucco	<input type="checkbox"/> Cobblestone	
<input type="checkbox"/> Aluminum Siding	<input type="checkbox"/> Concrete Type:	<input type="checkbox"/> Cut stone Type:	
9. STRUCTURAL SYSTEM			
<input checked="" type="checkbox"/> Wood frame	<input type="checkbox"/> Post and beam	<input type="checkbox"/> balloon	
<input type="checkbox"/> Load bearing masonry	<input type="checkbox"/> Structural iron or steel		
<input type="checkbox"/> Other (Specify)			
10. ROOF (Type)			
<input checked="" type="checkbox"/> Gable	<input type="checkbox"/> Flat	<input type="checkbox"/> Mansard	<input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth
<input type="checkbox"/> Gambrel	<input type="checkbox"/> Shed	<input type="checkbox"/> Hip	<input type="checkbox"/> Round <input type="checkbox"/> Other (Specify)
(Material)			
<input type="checkbox"/> Wood Shingle	<input type="checkbox"/> Roll Asphalt	<input type="checkbox"/> Tin	<input type="checkbox"/> Slate <input type="checkbox"/> Gable end to the street
<input checked="" type="checkbox"/> Asphalt shingle	<input type="checkbox"/> Built up	<input type="checkbox"/> Tile	<input type="checkbox"/> Other (Specify) <input checked="" type="checkbox"/> Ridge parallel to the street
11. NUMBER OF STORIES		APPROXIMATE DIMENSIONS	
2 1/2		36 x 30'	
12. CONDITION (structural)			
<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Deteriorated
(Exterior)		<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated
13. INTEGRITY (Location)			
<input checked="" type="checkbox"/> On original site	<input type="checkbox"/> Moved	WHEN	(Alterations)
			<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES			
<input checked="" type="checkbox"/> Barn	<input type="checkbox"/> Shed	<input type="checkbox"/> Garage	<input type="checkbox"/> Other landscape features or buildings (Specify)
<input type="checkbox"/> Carriage house	<input type="checkbox"/> Shop	<input type="checkbox"/> Garden	
15. SURROUNDING ENVIRONMENT			
<input type="checkbox"/> Open land	<input type="checkbox"/> Wood-land	<input checked="" type="checkbox"/> Residential	<input type="checkbox"/> Scattered buildings visible from site
<input type="checkbox"/> Commercial	<input type="checkbox"/> Indus-trial	<input type="checkbox"/> Rural	<input checked="" type="checkbox"/> High building density

DESCRIPTION

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS

On Thompson Hill, in a well preserved 19th century village center.

PHOTO	PHOTOGRAPHER Mark McDonough		DATE 1986
	VIEW NW	NEGATIVE ON FILE E22	
COMPILED BY	NAME Mark McDonough		DATE 1986
	ORGANIZATION Town of Thompson, Connecticut		
	ADDRESS		



20 SUBSEQUENT FIELD EVALUATION:

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

Four-bay facade, entry in third bay. Projecting right front gable, left front round tower. Tall double wood doors with large lights over panels. Paneled entry pilasters. Sash generally 2-over-2. One story full width porch extends to form rounded pavillion at left front.

Porch has paired square posts with infill panels with floral cut-outs. Post have plain capitals with turned circular bosses. Balusters generally square, turned and spindled to either side of entry steps. Molded rail.

Tower at left has paneled wall surface, molded cornice, conical roof with wood finial. Second floor has staggered-butt shingles. Right front gable has pedimented peak, paneled wall surface just below cornice, elliptical attic window with radical glazing, keyblock surround.

DESCRIPTION (Continued)

18 ARCHITECT	BUILDER
--------------	---------

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

This house, originally built by Talcott Crosby about 1827, was owned for several decades by Jeremiah Olney. Crosby (1795-1870) was a local farmer and merchant who also served for 35 years as Thompson Probate Judge.

Historically, the Talcott Crosby House is significant as part of a well preserved assemblage of older buildings in Thompson Hill.

Architecturally, the house is significant as one of several older houses in Thompson Hill remodelled in the last years of the 19th century, as the dormant turnpike trading center under went a second wave of popularity as a summer resort. The round tower and porch pavillion, the paneled wall surfaces, and the extravagant asymmetry of the facade are all typical of the Queen Anne style. The ornate porch detail and staggered butt shingles are seen in a wide variety of Victorian dwellings.

SIGNIFICANCE

SOURCES

1867 Atlas
Lincoln, Modern History of Windham County, p. 303-6
Thompson Land Records 10:46 (1826)

21 THREATS TO BUILDING OR SITE

<input checked="" type="checkbox"/> None known	<input type="checkbox"/> Highways	<input type="checkbox"/> Vandalism	<input type="checkbox"/> Developers	<input type="checkbox"/> Other _____
<input type="checkbox"/> Renewal	<input type="checkbox"/> Private	<input type="checkbox"/> Deterloration	<input type="checkbox"/> Zoning	<input type="checkbox"/> Explanaton _____