HISTORIC RESOURCES INVENTORY

BUILDING AND STRUCTURES HIST-6 NEW 5/77			00	FOR OFFICE USE ONLY
HIST-6 NEW 5/77		17	Town No.: Site No.:	
STATE OF CONNECTICUT				UTW I I I I I I I I I I I I I I I I I I I
	CONNECTICUT HISTORICAL COMMISSION 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106 (203) 566-3005			UTM
				QUAD:
3/75/5/ DISTRICT IF NR. SPECIF				
				S NR Actual Potential
IDENTIFICATION	1. BUILDING NAME (Common)	· 1	oric)	ng The Woulder
	2. TOWN CITY	VILLAGE	ASON PHIP	PS, JR. HOUSE
	THOMPSON	QUINEBAUG		WINDHAM
	3. STREET AND NUMBER (and or Focation)			
		NEBAUG RD.)		3/75-5
	4. OWNER(S)			
	Vinton, William H., Quinebaug, CT 5. USE (Present) (Hypere)			
	Residence (Historic)			
	6 EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIVE TO LE VES EXPLAIN			
	ACCESSIBILITY X Yes No	Yes X No		
	7 STYLE OF BUILDING			DATE OF CONSTRUCTION
DESCRIPTION	Vernacular/Federal			18th century
	8. MATERIALIS) (Indicate use or location when apple X Clapboard Asbestos Siding	Chimney	Other	
	X Clapboard Asbestos Siding	X Brick	☐ (Specify)	
	Wood Shingle Asphalt Siding X Fieldstone Foundation			
			Foundation	n
	Board & Batten Stucco	Cobblestone		
	Aluminum Concrete Siding Type:	Cut stone		
	9 STRUCTURAL SYSTEM			
	X Wood frame Post and beam	balloon		
	Load bearing masonry Structural iron or steel			
	Structural from or steel			
	Other Specify)			
	10 ROOF (Tvpr.)			
	X Gable Flat Man	sard Monitor	sawtooth	
	Gambrel Shed Hip	Round	Other (Spicify)	
	(Moterial)			
	- Roll			
SC	Wood Shingle Asphalt Tin	X Slote (rear	wing)	Gable end to the street
	X Asphalt shingle Built up Tile	Other (Specify)		X Ridge parallel to the street
	11. NUMBER OF STORIES APPROXIMATE DIMENS			
		main part)		
	12. CONDITION (Structural) (Exterior)			
	Excellent X Good Fair Deteriorated Excellent X Good Fair Deteriorated			
	12 INTEGRITY (Location) WHEN (Alterations) IF YES, EXPLAIN X On original			
	X site Moved X Yes No			
	Barn Shed Garage Other landscape features or buildings (Specify)			
	Carriage			
	☐ house ☐ Shop ☐ Garden			
	Open land Wood- X Residential Scattered buildings visible from site			
	☐ Open land ☐ Residential ☐ Scattered buildings visible from site			
Commercial Indus- Rural		X High buildi	ng density	
	16 INTERMELATIONSHIP OF BUILDING AND SURROUNDINGS			
	Near the later 19th century village center of Quinebaug.			

PHOTOGRAPHER