

**HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES**

HIST-6 NEW 5/77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
(203) 566-3005

289

67/53/4/1

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR. SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

| | | | | | |
|---|---|-------|--|--|-----------------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | | MECHANICSVILLE MILL HOUSING - TYPE A | | |
| | 2. TOWN CITY THOMPSON | | VILLAGE MECHANICSVILLE | COUNTY WINDHAM | |
| | 3. STREET AND NUMBER (and/or location) 2626 ROUTE 12 (95 RIVERSIDE DR.) | | 67/53-4 | | |
| | 4. OWNER(S) LANGEVIN, ROBERT E. & BARBARA J., MECHANICSVILLE, CT 06252 | | <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | |
| | 5. USE (Present) Residence | | (Historic) Residence | | |
| | 6. ACCESSIBILITY TO PUBLIC: | | EXTERIOR VISIBLE FROM PUBLIC ROAD <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | INTERIOR ACCESSIBLE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | IF YES, EXPLAIN |
| | 7. STYLE OF BUILDING Mill Housing | | DATE OF CONSTRUCTION C. 1875 | | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | | | | |
| | <input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input checked="" type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input type="checkbox"/> Cut stone Type: _____ | | | | |
| | 9. STRUCTURAL SYSTEM | | | | |
| | <input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____ | | | | |
| | 10. ROOF (Type) | | | | |
| | <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Gable end to the street <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Ridge parallel to the street | | | | |
| | 11. NUMBER OF STORIES | | APPROXIMATE DIMENSIONS | | |
| | 1 1/2 | | 46' x 26' | | |
| | 12. CONDITION (Structural) (Exterior) | | | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | | | | |
| 13. INTEGRITY (Location) | | WHEN? | (Alterations) | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved | | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES, EXPLAIN See #17 | | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input type="checkbox"/> Other landscape features or buildings (Specify) _____ <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | | | | |
| 15. SURROUNDING ENVIRONMENT | | | | | |
| <input type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input checked="" type="checkbox"/> High building density | | | | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | | | |
| In a row of very similar mill houses. | | | | | |

(OVER)

| | | | |
|-------------|---|-------------------------|--------------|
| PHOTO | PHOTOGRAPHER Mark McDonough | | DATE 1986 |
| | VIEW SE | NEGATIVE ON FILE F32 | |
| COMPILED BY | NAME Mark McDonough | | DATE 1986 |
| | ORGANIZATION Town of Thompson, Connecticut | | |
| | ADDRESS | | |



20 SUBSEQUENT FIELD EVALUATION:

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

SEE MASTER FORM FOR MECHANICSVILLE MILL HOUSING, TYPE A - 2608 ROUTE 12.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

SEE MASTER FORM FOR MECHANICSVILLE MILL HOUSING, TYPE A - 2608 ROUTE 12.

SOURCES

SEE MASTER FORM FOR MECHANICSVILLE MILL HOUSING, TYPE A - 2608 ROUTE 12.

21 THREATS TO BUILDING OR SITE

None known
 Highways
 Vandalism
 Developers
 Other _____

Renewal
 Private
 Deterioration
 Zoning
 Explanation _____